

Scope of work: Sections of the complex's underground network of storage rooms, hallways, and a main electrical room had been experiencing water infiltration. The waterproofing company that was contracted prepped the surfaces by cleaning them and using commercial dehumidifiers to dry the surfaces. They applied BondTAC 1500 to these affected areas and then painted over the protected surfaces.

