

BOND TAC

WATERPROOF MEMBRANES | SOLVENTS | CONTACT CEMENTS

PARAMOUNT HOTEL, NYC

Scope of work: Original parapet wall was damaged during storm and the copper cladding had been ripped off. Façade restoration company Benjamin Maintenance was contracted to assess damages, remove damaged sections, repair the damages and install new copper cladding. Benjamin Maintenance applied BondTAC 1500 on the cement layer of the parapet wall for waterproofing, air & vapor barrier, and adhesion. New copper cladding was installed over afterwards.

BOND TAC

Bondtac Technologies Incorporated

1 Imperial Court
Brampton, Ontario, Canada L6T 4X4

www.BOND TAC.com

